

Date: 6/16/16


Engineering Bulletin: 061602


Effective Date: Effective

Released By: Jon O'Neil

Subject: 4500 Series Deep Pocket Dies

Customers have experienced issues with having to recut transom glass down while using 4500 Series Storefront Entrances with transoms. This problem was caused by having two shallow glass pockets facing each other due to the way they where fabricated. To aleviate this issue, we have introduced two new extrusions to have deep pockets on both sides as our standard offering.





**HEAVYWALL**