

Date: 02/16/07

Engineering Bulletin: 020703

Effective Date: 02/16/07

Released By: Les Olds

Subject: 14000 I/O Door Frames

Description: Due to interference issues, 14000 I/O door frames ordered with a dead lock need to be specified with the P1422 short throw lock. The bolt of the P1420 is too long and hits the door jamb pocket filler.